

Keenan

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Art Rm 107

Priority: High

Description: Some of the ceiling shows water damage. The cause of the water damage should be identified and repairs should be made if necessary. The damaged ceiling should then be repaired.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Kiln Art 127

Priority: High

Description: Aisles and passageways were obstructed which could impede emergency egress. Aisles and passageways should be kept clear at all times and have a minimum width of 30 inches.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | AD/SS Bldg - Counseling & Matriculation AD103

Priority: High

Description: In an effort to avoid sexual assault/molestation concerns, office windows should not be obstructed with paper or other material. Blinds or window coverings should be open while students are present, especially during one-on-one staff-student interaction. Office doors should remain open as well.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - Basement

Priority: High

Description: Aisles and passageways were obstructed which could impede emergency egress. Aisles and passageways should be kept clear at all times and have a minimum width of 30 inches.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - Basement Mens Restroom

Priority: High

Description: Some of the ceiling in this area shows signs of water damage. The cause of the water damage should be identified and repairs should be made if necessary. The damaged ceiling should then be repaired.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Walkway by Parking Lot 10

Priority: High

Description: The open holes where the bollards were create a trip/fall hazard. The bollards should be replaced or the holes covered to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - 2nd Floor Hallway

Priority: High

Description: Some of the ceiling in this area shows signs of water damage. The cause of the water damage should be identified and repairs should be made if necessary. The damaged ceiling should then be repaired.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 131

Priority: High

Description: Compressed gas cylinders should always be secured in the upright position with a strong securing device such as a chain, strap or clamp.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Campus Center Bldg - Cafeteria Kitchen

Priority: High

Description: Some of the ceiling in this area show water damage. The cause of the water damage should be identified and repairs should be made if necessary. The damage should then be repaired.

Status: Open





Additional details: None


Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | North Hall Bldg - NH315-329

Priority: High

Description: In an effort to avoid sexual assault/molestation concerns, office windows should not be obstructed with paper or other material. Blinds or window coverings should be open while students are present, especially during one-on-one staff-student interaction. Office doors should remain open as well.

Status: Open





Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Overflow Parking

Priority: High

Description: The large open hole in the ground on the I-Street overflow parking lot creates a falling hazard. The large open hole should be covered or filled in to reduce this hazard.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Campus Center Bldg - Janitor Closet CC147.0

Priority: High

Description: The corroded or leaking pipes/water heater in this area should be repaired or replaced to reduce the possibility of flooding and water damage.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | PS Bldg - 3rd Floor Hallway

Priority: Medium

Description: Loose and/or broken ceiling tiles should be repaired or replaced to reduce the falling object hazard they present and maintain the fire barrier they create.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | PS Bldg - 3rd Floor Hallway

Priority: Medium

Description: The door in this location slams shut. The regulator on the door closing arm needs to be adjusted or repaired to reduce the stuck by hazard the door presents.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | PS Bldg - PS316

Priority: Medium

Description: Ladders should be stored secured in a manner that prevents tipping.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | PS Bldg - Architecture Room PS217

Priority: Medium

Description: Unsecured items leaning against the wall should be secured to prevent their accidental falling.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | PS Bldg - Astro Teaching Lab PS214

Priority: Medium

Description: The fire extinguisher was obstructed. The items should be moved or the fire extinguisher relocated to ensure access to the unit in an emergency.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Art Gallery

Priority: Medium

Description: The broke mirror should be repaired or replaced to reduce the laceration hazard that it presents.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Storage Art 108

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Ceramics Studio C2

Priority: Medium

Description: The broken tiles on the tub create a laceration hazard. The tiles should be repaired or replaced to reduce this hazard.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Ceramics Studio C2

Priority: Medium

Description: Damaged electrical outlets present an elevated risk of fire. Damaged electric outlets should be replaced to reduce this risk.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Ceramics Studio C2

Priority: Medium

Description: The large tub in this area creates a strain hazard when water buckets must be filled and lifted out. Consider replacing the tub with a smaller sink or multiple smaller sinks to reduce this risk.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Sculpture A120

Priority: Medium

Description: 1. The broken tiles on the tub create a laceration hazard. The tiles should be repaired or replaced to reduce this hazard. 2. The large tub in this area creates a strain hazard when water buckets must be filled and lifted out. Consider replacing the tub with a smaller sink or multiple smaller sinks to reduce this risk.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Workroom Art 119

Priority: Medium

Description: The sawdust collection system is inoperable. The system should be repaired or replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Workroom Art 119

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Art Room 144

Priority: Medium

Description: The floor outlet cover was broken and should be repaired or replaced to reduce the trip hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Art Bldg - Art Room 144

Priority: Medium

Description: Loose and/or broken ceiling tiles should be repaired or replaced to reduce the falling object hazard they present and maintain the fire barrier they create.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | AD/SS Bldg - Electrical Room 100F

Priority: Medium

Description: A minimum 36" clearance zone should be maintained around the electrical panel(s) at all times. Excessive or improper storage of items near the electrical panel(s) may lead to inaccessibility, an increased risk of fire, and may affect the lifespan of the electrical equipment.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | AD/SS Bldg - Conference Room 2 AD207

Priority: Medium

Description: The rug is covering the door stops creating a trip hazard. The rug should be moved or replaced with a smaller rug to reduce the hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - Outside Workshop A107

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Auditorium Bldg - Workshop A107

Priority: Medium

Description: The fire extinguisher was obstructed. The items should be moved or the fire extinguisher relocated to ensure access to the unit in an emergency.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - Workshop A107

Priority: Medium

Description: Due to the use of hazardous substances in this area, an emergency eyewash station and/or deluge shower is recommended.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - 2nd Floor

Priority: Medium

Description: The crawl space is open and accessible. The crawl space should be secured to eliminate any unauthorized access to this location.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - 3rd Floor

Priority: Medium

Description: The crawlspace is open and accessible. The crawlspace should be secured to eliminate any unauthorized access to this location.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - Basement Equipment Room

Priority: Medium

Description: The protruding wall bolts should be cut flush and filed smooth to reduce the hazard and reduce the risk of injury.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - Prop Room A022 Costume Shop

Priority: Medium

Description: 1. Housekeeping should be improved. The area should be kept in a clean and orderly condition. Aisles and passageways should be kept clear and in good repair. 2. A minimum 18" of clearance should be maintained from stored items to ceiling mounted automatic sprinkler heads at all times.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - A023 Recycling Room

Priority: Medium

Description: Housekeeping should be improved. The area should be kept in a clean and orderly condition. Aisles and passageways should be kept clear and in good repair.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Auditorium Bldg - A002 Equipment

Priority: Medium

Description: Clear access to the fire sprinkler system riser should be maintained at all times.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - High Power Electricity Lab 239

Priority: Medium

Description: A minimum 18" of clearance should be maintained from stored items to ceiling mounted automatic sprinkler heads at all times.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - High Power Electricity Lab 239

Priority: Medium

Description: Ladders should be stored secured in a manner that prevents tipping.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - High Power Electricity Lab 239

Priority: Medium

Description: The unsecured bookcases and storage cabinets present an elevated risk of struck by injuries. They can also block emergency egress if they tip over. Bookcases and storage cabinets should be secured in a manner that prevents them from tipping over to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Industrial Automation Lab 241

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Industrial Automation Lab 241

Priority: Medium

Description: The heavy items stored on top of cabinets or overhead shelves present an elevated risk of struck by injuries. They can also block emergency egress if they fall to the floor. Heavy items should be stored at a lower level to reduce this hazard. Other items stored overhead should be secured in a manner that prevents them from falling.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Electronic Lab 247

Priority: Medium

Description: Connecting extension cords and/or multi-outlet power strips end to end presents an elevated risk of fire or circuit overload.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Electronic Lab 247

Priority: Medium

Description: A fire extinguisher should be provided for this area.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Electronic Lab 251

Priority: Medium

Description: A fire extinguisher should be provided for this area.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Building Wide

Priority: Medium

Description: The metal guard near the eyewash station creates a trip hazard and should be painted a high-visibility color to reduce the hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - HVAC & R Lab 255

Priority: Medium

Description: The eyewash station and/or deluge shower was obstructed. Clear access should be maintained at all times.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - HVAC & R Lab 255

Priority: Medium

Description: Aisles and passageways were obstructed which could impede emergency egress. Aisles and passageways should be kept clear at all times and have a minimum width of 30 inches.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - HVAC & R Lab 255

Priority: Medium

Description: The fire extinguisher was obstructed. The items should be moved or the fire extinguisher relocated to ensure access to the unit in an emergency.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Applied Tech Bldg - Machine Lab 118

Priority: Medium

Description: Extension cords are not designed for permanent use. The extension cord should be replaced with permanent wiring in accordance with the National Electric Code.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Machine Lab 118

Priority: Medium

Description: Electrical cords on the floor creates a trip hazard in this area. The cords should be rerouted or covered with a cord cover/protector to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Machine Lab 118

Priority: Medium

Description: Chemicals should be stored at or below eye level to allow safe handling of chemicals. If this is not possible and higher storage is required, then an appropriate sized sturdy ladder, stool or portable step should be provided.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Machine Lab 118

Priority: Medium

Description: Oil spills should be cleaned up immediately using a spill absorbent or another approved substance. Oil contaminated spill absorbent is considered hazardous waste and should be disposed of properly.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Grinder 118A

Priority: Medium

Description: Grinders should be inspected regularly to ensure that tongue guards, tool rests, and safety shields are attached and adjusted properly. If equipment is broken or missing, it should be taken out of service until it is repaired or replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Applied Tech Bldg - Elev. Control Room 149

Priority: Medium

Description: A fire extinguisher should be provided for this area.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Heavy Truck Engine Lab 158

Priority: Medium

Description: Ladders should be stored secured in a manner that prevents tipping.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Hybrid & EV Lab 133

Priority: Medium

Description: Electrical cords on the floor creates a trip hazard in this area. The cords should be rerouted or covered with a cord cover/protector to reduce this hazard.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Applied Tech Bldg - Outdoor Collision Lab

Priority: Medium

Description: Installation hose reels should be installed to reduce clutter and trip hazards.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 131

Priority: Medium

Description: The vehicle body being welded is supported by pallets, creating an unstable work environment and a potential fire hazard. The vehicle should be secured on appropriate equipment designed for this purpose to reduce this risk of injury or fire.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 131

Priority: Medium

Description: Portable fire extinguishers should be wall mounted in an easily accessible location. The distance between fire extinguishers should be no more than 75'.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 131

Priority: Medium

Description: There was a car part that had nails sticking out created a protrusion or laceration hazard. The part should be repaired or stored in a secure area until needed.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 131

Priority: Medium

Description: The work tabletop is constructed from a splintered piece of plywood placed on a wheeled frame, making the work area unstable and creating potential safety hazards. This setup should be removed or replaced with a standard work table.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 131

Priority: Medium

Description: A piece of wood with a protruding bolt is located in the walkway, creating a safety hazard. This material should be removed from the area to eliminate the risk of injury.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Applied Tech Bldg - Room 127 Storage

Priority: Medium

Description: An approved flammable liquid storage cabinet should be provided in this area.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: Electrical cords on the floor creates a trip hazard in this area. The cords should be rerouted or covered with a cord cover/protector to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: Chemical storage areas, prep areas and labs should be clearly posted with signage stating, "NO EATING OR DRINKING". This rule should be strictly enforced for students and staff.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: Aisles and passageways were obstructed which could impede emergency egress. Aisles and passageways should be kept clear at all times and have a minimum width of 30 inches.

Status: Open





Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: The fire extinguisher was obstructed. The items should be moved or the fire extinguisher relocated to ensure access to the unit in an emergency.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: Benchtop and pedestal-mounted equipment such as grinders, miter saws, and drill presses should be secured to a bench or the floor to prevent tipping.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: Heavy items stored on top of cabinets or overhead shelves present an elevated risk of struck by injuries. They can also block emergency egress if they fall to the floor. Heavy items should be stored at a lower level to reduce this hazard. Other items stored overhead should be secured in a manner that prevents them from falling.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Technology Bldg - T114A Aeronautics Lab

Priority: Medium

Description: Students were noted to have not been wearing PPE in this area during the inspection. Appropriate PPE should be required and utilized when persons work with equipment, chemicals, or in areas that present an elevated risk of injury.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Technology Bldg - Welding Lab T112B

Priority: Medium

Description: Electrical cords on the floor creates a trip hazard in this area. The cords should be rerouted or covered with a cord cover/protector to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Outside Technology Bldg

Priority: Medium

Description: Raised or cracked sections of asphalt/concrete present a trip hazard and should be repaired to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Campus Center Bldg - Sunroom Kitchen

Priority: Medium

Description: When HVAC vents are dirty reduces free airflow and efficiency of the system. Any items that obstruct or block airflow should be removed or cleaned immediately.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Campus Center Bldg - Sunroom Kitchen

Priority: Medium

Description: Fire extinguisher locations should be clearly marked with a sign or label.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Campus Center Bldg - Cafeteria Kitchen

Priority: Medium

Description: The ladder allows access to the roof and should be removed to reduce the risk or unauthorized access to the ladder and roof.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Business Bldg - Room 100A

Priority: Medium

Description: The classroom doors should remain closed and locked when not in use to prohibit unauthorized access and deter theft.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Business Bldg - Room 100A

Priority: Medium

Description: There appears to have been a fire in this room. The cause of the fire should be determined and the damages repaired.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Business Bldg - Room 100A

Priority: Medium

Description: The fire extinguishers were obstructed by the room partition. The room's fire extinguishers should be relocated to ensure access to the unit in an emergency.

Status: Open




Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Business Bldg - Room 131

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Business Bldg - Room 216

Priority: Medium

Description: The classroom doors should remain closed and locked when not in use to prohibit unauthorized access and deter theft.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Business Bldg - 212 Computer Lab

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Business Bldg - Second Floor Walkway

Priority: Medium

Description: Exit routes are not clearly identified in this area. Exit way-finding signage should be provided.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Business Bldg - Room 214

Priority: Medium

Description: The classroom doors should remain closed and locked when not in use to prohibit unauthorized access and deter theft.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | KVCR
Bldg - Admission Corridor MC 107

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | KVCR
Bldg - TV Production Suite MC 143

Priority: Medium

Description: The fire extinguisher was obstructed. The items should be moved or the fire extinguisher relocated to ensure access to the unit in an emergency.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Campus Center Bldg - Student Lounge 128.0

Priority: Medium

Description: The exterior door when shut has a large gap that allows pest to come into this location. The gap between the two doors should be address to help reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Library Bldg - Lib 149

Priority: Medium

Description: Damaged electrical outlets present an elevated risk of fire. Damaged electric outlets should be replaced to reduce this risk.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Library Bldg - Conference Room LIB 148

Priority: Medium

Description: Some of the ceiling tiles in this area are water stained. The cause of the water stain should be identified and repairs should be made if necessary. The damaged tile should then be replaced.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | North
Hall Bldg - Sound Lock NH 164

Priority: Medium

Description: Electrical cords on the floor creates a trip hazard in this area. The cords should be rerouted or covered with a cord cover/protector to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Planetarium Office 105

Priority: Medium

Description: The electric space heaters left on and unattended present an elevated risk of fire. No portable heater should be left on while unattended.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Overflow Parking

Priority: Medium

Description: Raised or cracked sections of asphalt/concrete present a trip hazard and should be repaired to reduce this hazard.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE |
Campus Center Bldg - Equipment Storage CC148.0

Priority: Medium

Description: 1. The heavy items stored on top of cabinets or overhead shelves present an elevated risk of struck by injuries. They can also block emergency egress if they fall to the floor. Heavy items should be stored at a lower level to reduce this hazard. Other items stored overhead should be secured in a manner that prevents them from falling. 2. A minimum 18" of clearance should be maintained from stored items to ceiling mounted automatic sprinkler heads at all times.

Status: Open



Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | AD/SS Bldg - Financial Aid 106

Priority: Medium

Description: There is evidence of rodent infestation in this area. This can lead to damage of wires, insulation, and other electrical components. The infestation should be addressed to reduce the potential for fire or equipment breakdown.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Village Portables

Priority: Medium

Description: Per staff, there is evidence of rodent infestation in this area. This can lead to damage of wires, insulation, and other electrical components. The infestation should be addressed to reduce the potential for fire or equipment breakdown.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Campus Center Bldg - Veterans Resource Center

Priority: Medium

Description: There is evidence of rodent infestation in this area. This can lead to damage of wires, insulation, and other electrical components. The infestation should be addressed to reduce the potential for fire or equipment breakdown.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Campus Center Bldg - Veterans Resource Center

Priority: Medium

Description: There is evidence of rodent infestation in this area. This can lead to damage of wires, insulation, and other electrical components. The infestation should be addressed to reduce the potential for fire or equipment breakdown.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Football Field Concession Stand

Priority: Medium

Description: Per staff, there was evidence of rodent infestation in this area. This can lead to damage of wires, insulation, and other electrical components. The infestation should be addressed to reduce the potential for fire or equipment breakdown.

Status: Open

Additional details: None

Location: SWACC | San Bernardino Community College | SAN BERNARDINO VALLEY COLLEGE | Football Field Concession Stand

Priority: Medium

Description: Per staff, there was evidence of rodent infestation in this area. This can lead to damage of wires, insulation, and other electrical components. The infestation should be addressed to reduce the potential for fire or equipment breakdown.

Status: Open

Additional details: None
